





1/19



2/19




Figure 1E




Figure 1F

3/19

16

16




Figure 2A

Figure 2B




Fig. 2C

34

Fig. 2D

Fig 3A

16 →




Fig 3B

16 →





Fig 3C

16 →



5/19






Figure 4



7/19




Fig 5B

8/19




Figure 6

9/19




Fig. 7




Figure 8A




Figure 8B






Figure 9B






Figure 10C





FIG. 10D

16/19



Foot Stirrup
w/Connecting Ring

Figure 11




FIG. 13A




FIG. 12




Figure 13B

19/19




Figure 14